

Download Humidity Log Standards 2013

Humidity is the amount of water vapour present in air. Water vapour, the gaseous state of water, is generally invisible to the human eye. Humidity indicates the likelihood for precipitation, dew, or fog to be present. The amount of water vapour needed to achieve saturation increases as the temperature increases. A humidity indicator card (HIC) is a card on which a moisture-sensitive chemical is impregnated such that it will change color when the indicated relative humidity is exceeded. This has usually been a blotting paper impregnated with cobalt(II) chloride base; Less toxic alternatives include other chemicals such as Cobalt-free chloride base and special plastic films. ©2019 The Joint Commission, All Rights Reserved

does anyone know where i can find info on what a cmm rooms has to be at as far as temp and humidity. i'm trying show management that our results will repeat better if we keep a constant and would like to have my ammo before i go to the fight i was always told 68 degrees plus or minus 2 for temp. is there a call out for iso or anything? thanks