

Download Kdi 572 Installation Manual

A complete DME installation requires a KN 63 DM E (066-1070-00/01), a KDI 572 master indicator (066-1069-00 or 01) or KDI 574 Master Indicator (066-1069-04), a KA 60/61 antenna, and one or two external control heads (see section 1.3, channeling sources). Kdi 572 installation manual also by category and product type, so for example, you could start learning about online user manuals for many cameras or saws, and after that dig into narrower sub categories and topics. The top-quality KDI 572 distance measuring equipment (DME) master display controls and displays information from a remote DME transmitter/receiver. It displays distance, groundspeed, and time-to-station all at the same time. Slant-range distance is computed digitally and displayed up to the maximum range of 399 nautical miles. Find great deals on eBay for kdi 572. Shop with confidence. Skip to main content. eBay Logo: Shop by category. ... KDI-573 & KDI-574 Indicator Install Manual. Pre-Owned. \$81.75. Buy It Now +\$4.31 shipping. Bendix/King KDI 572 DME Indicator - GRAY. Pre-Owned. \$995.00. or Best Offer. Free Shipping.